


MS3711




Pin Assignment

Pin NO.	Signal Name
1	P(+)
2	N(-) POWER
PE	GND
4	+ OUTPUT 1
5	- OUTPUT 1
6	N.C.
7	+ OUTPUT 2
8	- OUTPUT 2
9	+ INPUT
10	- INPUT
11	EX

1出力型の場合、端子の7,8番ピンはN.C.となります。

Pin Location



単位:mm