



MS3719



Pin Assignment

Pin NO.	Signal Name
1	P(+)
2	N(-)
POWER	
PE	GND
4	+ OUTPUT
5	- OUTPUT
6	EX +
7	EX GND
8	EX -
9	+ INPUT
10	SIG GND
11	- INPUT

Pin Location



単位:mm