


MS3900-TH



Pin Assignment

SOCKET	PIN NO.	SIGNAL NAME
1	1	+ INPUT
	2	-
	3	N.C.
	4	N.C.
	5	N.C.
	6	N.C.
2	1	+ OUTPUT-1
	2	-
	3	+ OUTPUT-2
	4	-
	5	N.C.
	6	N.C.
	7	N.C.
	8	N.C.
	9	N.C.
	10	N.C.

単位: mm